

## Brake Pad Cross Reference

Courtesy of Hawk Brake Pad

To order, contact Racer Parts Wholesale: 1-800-397-7815 or [www.racerpartswholesale.com](http://www.racerpartswholesale.com)

| Hawk Part # | PFC Part # | Wilwood # | Mintex    | Ferodo Part # |
|-------------|------------|-----------|-----------|---------------|
| HB 100.480  | 7752**12.4 | 7112      | MTX-1796  | FRP502        |
| HB 100.625  | 7752**16.4 |           |           |               |
| HB 101.800  | 7751**20.4 | 7320      | MTX-1795  | FRP501        |
| HB 102.800  | 7753**21.4 | 7520      | MTX-1798  | FRP503        |
| HB 103.590  | 052**14.4  | D52       |           | FRP3057       |
| HB 104.485  | 7757**12.4 | 7012      | MTX-1809  | FRP506        |
| HB 105.630  | 7700**16.4 | 9216      |           | FRP1077       |
| HB 105.708  | 7700**18.4 |           |           | FRP3007       |
| HB 105.775  | 7700**20.4 | 9220      | MTX-1697  | FRP302        |
| HB 105.980  | 7700**25.4 |           |           | FRP1078       |
| HB 106.980  | 7702**25.4 | 9425      | MTX-1247  |               |
| HB 1061.12  | 7702**28.4 | 9428      | MTX-1247  | FRP3059       |
| HB 107.620  | 7740**16.4 |           | MTX-1200  | FRP218        |
| HB 108.560  | 7720**15.4 |           | MTX-MLB20 | FCP825        |
| HB 109.710  | 7790**18.4 |           |           | FRP3003       |
| HB 109.785  | 7790**20.4 | 8820      |           |               |
| HB 109.980  | 7790**25.4 | 8825      | MTX-1850  | FRP3014       |
| HB 1091.12  | 7790**29.4 | 8828      | MTX-1850  | FRP3015       |
| HB 110.654  | 7767**17.4 | 8517      | MTX-1292  | FRP216        |
| HB 110.775  | 7767**21.4 |           | MTX-1289  | FRP212        |
| HB 111.610  | 412**16.4  | D412      | MTX-1766  | FCP1224       |
| HB 111.660  | 412**17.4  |           |           |               |
| HB 111.720  |            |           |           |               |
| HB 112.540  | 413**13.4  | D413      | MTX-1767  |               |
| HB 113.590  | 373**17.4  |           |           | FCP598        |
| HB 114.980  | 7714**25.4 |           |           | FRP217        |
| HB 115.630  | 7710**16.4 |           | MTX-1541  | FRP101        |
| HB 116.580  | 7765**15.4 |           | MTX-MLB65 | FCP840        |
| HB 117.380  | 7719**11.4 |           | MTX-MLB19 | FCP342        |
| HB 118.560  | 044**15.4  |           |           | FCP809        |
| HB 119.594  | 154**14.4  | D154      |           | FRP3058       |
| HB 120.560  |            |           |           |               |
| HB 121.710  | 7794**18.4 | 8618      |           | FRP3000       |
| HB 121.785  | 7794**20.4 | 8620      |           |               |
| HB 121.980  | 7794**25.4 |           |           | FRP1060       |
| HB 122.710  | 7793**18.4 |           |           | FRP3054       |
| HB 122.980  | 7793**25.4 |           |           |               |
| HB 123.535  |            |           | MTX-MLB37 | FCP824        |
| HB 125.650  |            |           |           |               |
| HB 126.546  | 008**13.4  | D8        |           |               |
| HB 128.530  |            |           |           |               |
| HB 130.775  | 7770**20.4 | 9720      |           | FRP3024       |
| HB 130.980  | 7770**26.4 | 9726      |           |               |
| HB 1301.03  | 7770**28.4 | 9728      |           | FRP3029       |
| HB 131.595  | 614**14.4  |           |           |               |
| HB 132.580  |            |           |           | FCP823        |

## Brake Pad Cross Reference

Courtesy of Hawk Brake Pad

To order, contact Racer Parts Wholesale: 1-800-397-7815 or [www.racerpartswholesale.com](http://www.racerpartswholesale.com)

| Hawk Part # | PFC Part # | Wilwood # | Mintex   | Ferodo Part #   |
|-------------|------------|-----------|----------|-----------------|
| HB 134.665  | 292**17.4  |           |          | FCP593          |
| HB 134.706  |            |           |          | FCP845          |
| HB 135.642  |            |           |          |                 |
| HB 135.700  |            |           |          |                 |
| HB 135.770  | 394**20.4  |           |          | FCP779          |
| HB 136.690  | 558**17.4  |           |          | FCP725          |
| HB 137.690  | 395**20.4  |           |          | FCP256          |
| HB 137.690  | 253**19.4  |           |          |                 |
| HB 138.690  |            |           |          | FCP584/1067     |
| HB 141.650  | 447**17.4  |           |          |                 |
| HB 141.709  |            |           |          | FCP560          |
| HB 142.525  | 382**14.4  |           |          | FCP408          |
| HB 143.680  |            |           |          | FCP905          |
| HB 144.690  |            |           |          |                 |
| HB 144.719  |            |           |          | FCP777/904      |
| HB 145.570  |            |           |          | FCP956          |
| HB 148.560  |            |           |          |                 |
| HB 149.505  |            |           |          |                 |
| HB 150.555  |            |           |          |                 |
| HB 151.505  |            |           |          |                 |
| HB 152.540  |            |           |          |                 |
| HB 155.580  | 463**15.4  |           |          |                 |
| HB 156.562  |            |           |          |                 |
| HB 157.484  |            |           |          |                 |
| HB 158.515  | 482**13.4  |           |          |                 |
| HB 159.492  |            |           |          |                 |
| HB 167.620  | 7735**16.4 | 8316      | MTX-1553 | FRP1079         |
| HB 167.778  | 7735**20.4 | 8320      | MTX-1553 | FRP308          |
| HB 167.870  | 7735**22.4 |           | MTX-1553 | FRP3041         |
| HB 168.670  |            |           |          | FRP1058         |
| HB 168.770  | 7748**20.8 | 8220      |          | FRP1064         |
| HB 169.560  |            |           |          |                 |
| HB 170.650  | 345**17.4  |           |          |                 |
| HB 170.710  | 7725**18.4 |           |          | FCP451          |
| HB 170.950  | 7725**24.4 |           |          |                 |
| HB 171.590  | 045**15.4  |           |          | FCP11           |
| HB 171.720  | 045**19.4  |           |          |                 |
| HB 172.500  |            |           |          |                 |
| HB 172.595  | 031**15.4  |           |          | FCP2/105        |
| HB 173.595  |            |           |          |                 |
| HB 175.560  | 051**15.4  |           |          | FCP810          |
| HB 176.680  | 641**17.4  |           |          |                 |
| HB 177.630  | 642**17.4  |           |          |                 |
| HB 178.564  | 460**14.4  |           |          | FCP986          |
| HB 179.630  | 461**16.4  |           |          | FCP1372         |
| HB 180.591  | 109**14.4  |           |          | FRP3056/FCP1282 |

## Brake Pad Cross Reference

Courtesy of Hawk Brake Pad

To order, contact Racer Parts Wholesale: 1-800-397-7815 or [www.racerpartswholesale.com](http://www.racerpartswholesale.com)

| Hawk Part # | PFC Part # | Wilwood # | Mintex   | Ferodo Part #   |
|-------------|------------|-----------|----------|-----------------|
| HB 180.640  | 174**16.4  |           |          | FCP116          |
| HB 181.660  | 639**17.4  |           |          | FCP1298         |
| HB 182.660  | 600**18.4  |           |          | FCP1247         |
| HB 183.585  | 627**15.4  |           |          |                 |
| HB 183.660  |            |           |          |                 |
| HB 184.650  | 594**18.4  |           |          | FCP891          |
| HB 184.710  |            |           |          |                 |
| HB 184.915  | 594**24.4  |           |          | FRP3042         |
| HB 185.590  |            |           |          |                 |
| HB 186.670  |            |           |          |                 |
| HB 186.770  | 7743**20.8 | 8020      |          | FRP3022         |
| HB 187.630  | 7755**16.4 |           | MTX-1800 | FRP3009         |
| HB 187.780  | 7755**20.4 |           | MTX-1800 | FRP3012         |
| HB 188.630  | 7709**16.8 |           |          |                 |
| HB 189.550  | 280**15.4  |           |          |                 |
| HB 189.595  |            |           |          | FCP392          |
| HB 189.760  | 280**19.4  |           |          |                 |
| HB 190.600  |            |           |          | FCP774          |
| HB 190.730  |            |           |          | FCP775          |
| HB 191.590  | 242**15.4  |           |          | FCP308          |
| HB 192.620  | 7745**16.4 | 8716      |          | FRP219          |
| HB 193.670  | 7780**18.4 |           |          | FRP3028/FCP1281 |
| HB 194.570  | 592**17.4  |           |          | FCP1348         |
| HB 194.665  |            |           |          | FCP721          |
| HB 195.640  | 278**17.4  |           |          | FCP303/546      |
| HB 195.730  |            |           |          | FCP1133         |
| HB 198.565  |            |           |          |                 |
| HB 198.685  | 252**18.4  |           |          |                 |
| HB 199.660  |            |           |          |                 |
| HB 199.702  | 443**18.4  |           |          |                 |
| HB 200.670  | 7742**20.8 | 8120      |          | FRP3004         |
| HB 200.830  | 7742**22.8 |           |          | FRP1059/3034    |
| HB 201.620  |            |           |          |                 |
| HB 202.580  | 282**90.4  |           |          |                 |
| HB 203.550  |            |           |          |                 |
| HB 204.615  |            |           |          |                 |
| HB 206.565  | 082**15.4  |           |          |                 |
| HB 208.708  | 7718**18.4 |           |          | FRP3016         |
| HB 209.583  |            |           |          |                 |
| HB 211.634  |            |           |          |                 |
| HB 212.535  |            |           |          |                 |
| HB 213.626  |            |           |          |                 |
| HB 214.618  |            |           |          | FCP765          |
| HB 215.630  | 629**16.4  |           |          |                 |
| HB 216.590  | 630**15.4  |           |          |                 |
| HB 217.681  | 623**18.4  |           |          |                 |

## Brake Pad Cross Reference

Courtesy of Hawk Brake Pad

To order, contact Racer Parts Wholesale: 1-800-397-7815 or [www.racerpartswholesale.com](http://www.racerpartswholesale.com)

| Hawk Part # | PFC Part # | Wilwood # | Mintex   | Ferodo Part #   |
|-------------|------------|-----------|----------|-----------------|
| HB 218.583  | 273**15.4  |           |          | FCP708          |
| HB 219.634  |            |           |          |                 |
| HB 221.980  |            |           | MTX-2020 |                 |
| HB 2211.12  | 7775**28.4 | 9828      | MTX-2020 | FRP3053         |
| HB 222.980  |            |           |          |                 |
| HB 2221.12  |            |           |          |                 |
| HB 224.980  | 7712**25.4 | 9525      |          |                 |
| HB 2241.12  | 7712**28.4 | 9528      |          | FRP3060         |
| HB 225.630  | 7708**16.8 |           |          | FRP1061         |
| HB 226.650  | 7768**16.4 |           |          | FRP3018/3043    |
| HB 227.630  | 396**17.4  |           |          | FCP578/850      |
| HB 229.580  |            |           |          | FCP832          |
| HB 230.625  |            |           |          |                 |
| HB 231.625  |            |           |          |                 |
| HB 235.665  |            |           |          | FCP600          |
| HB 236.622  |            |           |          |                 |
| HB 237.480  |            | 7212      |          | FRP504          |
| HB 237.625  | 7754**16.4 | 7216      |          |                 |
| HB 2381.18  | 7683**30.4 | 9930      |          | FRP3025/3052    |
| HB 242.661  |            |           |          | FCP748          |
| HB 243.705  |            |           |          | FCP406/604/1063 |
| HB 244.624  |            |           |          | FCP9            |
| HB 245.631  | 617**17.4  |           |          | FCP1436         |
| HB 246.567  |            |           |          | FCP487          |
| HB 247.575  | 731**15.4  | D731      |          |                 |
| HB 248.650  | 732**17.4  | D732      |          |                 |
| HB 249.575  |            |           |          |                 |
| HB 250.653  |            |           |          |                 |
| HB 261.665  |            |           |          | FCP600          |
| HB 262.540  |            |           |          |                 |
| HB 263.650  | 431**15.4  | D431      |          |                 |
| HB 265.685  |            |           |          |                 |
| HB 268.665  | 526**17.4  |           |          | FCP1430         |
| HB 269.763  |            |           |          | FCP590/1068     |
| HB 270.724  |            |           |          |                 |
| HB 271.605  |            |           |          | FCP541          |
| HB 272.763  |            |           |          |                 |
| HB 274.610  |            |           |          |                 |
| HB 275.620  |            |           |          | FCP761          |
| HB 275.660  |            |           |          |                 |
| HB 275.720  |            |           |          |                 |
| HB 276.780  | 7802**20.8 |           |          |                 |
| HB 276.830  |            |           |          |                 |
| HB 278.583  | 491**15.4  |           |          | FCP878          |
| HB 289.610  |            |           |          | FCP1307         |
| HB 290.583  |            |           |          |                 |

## Brake Pad Cross Reference

Courtesy of Hawk Brake Pad

To order, contact Racer Parts Wholesale: 1-800-397-7815 or [www.racerpartswholesale.com](http://www.racerpartswholesale.com)

| Hawk Part # | PFC Part # | Wilwood # | Mintex   | Ferodo Part # |
|-------------|------------|-----------|----------|---------------|
| HB 290.606  | 738**17.4  |           |          | FCP1308       |
| HB 291.642  | 776**16.4  |           |          | FRP3051       |
| HB 310.689  |            |           |          | FCP867        |
| HB 318.669  |            |           |          |               |
| HB 319.669  |            |           |          | FCP868        |
| HB 320.669  |            |           |          | FCP1437       |
| HB 321.650  |            |           |          |               |
| HB 325.720  |            |           |          | FCP856        |
| HB 328.685  |            |           |          |               |
| HB 329.543  |            |           |          | FRP3038       |
| HB 3301.17  |            |           |          | FRP3046       |
| HB 331.886  | 7773**22.4 |           | MTX-2016 | FRP3047       |
| HB 3311.17  | 7773**30.4 | 8430      | MTX-2016 | FRP3040       |
| HB 339.856  | 7810**22.8 |           |          | FRP3048       |
| HB 340.710  | 7818**18.4 |           |          | FRP3050       |
| HB 340.945  | 7818**24.4 |           |          |               |
| HB 346.713  |            |           |          |               |
| HB 3481.14  | 7797**29.4 |           |          | FRP3031       |
| HB 349.980  | 7778**25.4 |           |          | FRP3039       |
| HB 3491.18  | 7778**30.5 |           |          | FRP3055       |
| HB 350.496  |            |           |          |               |
| HB 352.665  |            |           |          |               |
| HB 354.701  |            |           |          |               |
| HB 354.756  |            |           |          |               |